



The Municipality of Lambton Shores

9577 Port Franks Road, Thedford ON
Telephone: (519) 243-1400
Email: awilliams@lambtonshores.ca
[The Municipality of Lambton Shores](http://www.lambtonshores.ca)

RFP 2026-23 Engineering Services for Forest I&I Study Update Addendum No. 1

The Following questions have been received:

Question 1: Does an interested firm need to be registered with the Municipality or any third-party site in order to submit a proposal / bid?

Answer 1: Interested firms do not need to register to submit a proposal for this project

Question 2: Is there a required standard or format for the maintenance hole inspections (for instance PACP Level 1 or Level 2)?

Answer 2: Maintenance Hole inspections are to be **PACP Level 1**. Field crews are (at a minimum) required to assess the following

- Frame and Grate / Cover Condition
 - Structural condition of the frame, grate, and ladder
 - Interior Barrel condition, including any cracking or deterioration
 - Benching, parging, and channel condition
 - Evidence of surcharge, debris accumulation, or other deficiencies
 - Evidence of infiltration through joints, pipes, or walls
 - Evidence of improper connections
-

September 9, 2026

_____ Proponent's Signature	_____ Date
<i>(Bidders shall sign and date all addenda and attach copies to the submitted Proposal)</i> <i>(emailed to all registered Plan Takers –1 page)</i>	

